From:

Steve Demczak

To:

Angela Nance; Dennis Ware; Suzanne Steab

Date:

8/3/2010 7:08 AM

 Subject:
 July Insp. Report

 Attachments:
 20100803072451.pdf; 20100803072507.pdf; 20100803072427.pdf



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENES. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

ıtativ	es Present During the Inspection:	
any	Dennis Ware	
GM	Steve Demczak	
	any	ntatives Present During the Inspection: any Dennis Ware GM Steve Demczak

Inspection Report

Permit Number:	C0070006		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, July 21, 2010		
Start Date/Time:	7/21/2010 10:00:00 AM		
End Date/Time:	7/21/2010 12:00:00 PM		
Last Inspection:	Tuesday, June 22, 2010		

Inspector: Steve Demczak. Weather: Sunny, 90's

InspectionID Report Number: 2432

☐ Reprocessing

Accepted by: jhelfric

7/29/2010

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	8,885.00			
Total Disturbed	87.30			
Phase I	95.30			
Phase II	95.30			
Phase III	8.00			

Mineral	Ownership
---------	-----------

Types of Operations ✓ Federal ✓ Underground **✓** State ☐ Surface ☐ Loadout County Processing ☐ Other

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

The permittee has pulled out subsidence survey marker throughout the permit area.

Inspector's Signature:

Date

Wednesday, July 21, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspection Type: PARTIAL

Inspection Date: Wednesday, July 21, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.

 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not

 appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

1.	Pormite Observe Tour ()	Evaluated	Not Applicable	Comment	Enforcemen
_	Permits, Change, Transfer, Renewal, Sale	✓		<u> </u>	
2.	Signs and Markers	V		\checkmark	
3.	Topsoil	✓		V	
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		V		
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring			. 🗆	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments			$\overline{\Box}$	
8.	Noncoal Waste	V		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	V		V	$\overline{\Box}$
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	V		V	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls		П	П	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V		<u> </u>	
	AVS Check	П	<u>_</u>		
20.	Air Quality Permit				
	Bonding and Insurance				
	Other				

Inspection Continuation Sheet

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Wednesday, July 21, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

Conoco Philips has started building a pad on the 40 acres they acquired from Plateau.

2. Signs and Markers

The identification signs is next to the road to the site.

3. Topsoil

All topsoil was used for reclamation.

4.a Hydrologic Balance: Diversions

Diversions were spot-checked and were functioning as designed. No major storms have taken place since the last inspection.

8. Noncoal Waste

The site was clear of non-coal waste material.

10. Slides and Other Damage

No slides or other damage were noticed during the inspection.

12. Backfilling And Grading

The disturb area is completely backfilled and graded. The permittee received Phase II bond release from the Division.

18. Support Facilities, Utility Installations

No suport facilities at this site.